
BRASS FITTINGS

D.O.T. AIR BRAKE - COPPER TUBING

MALE BRANCH TEE

SAE# 120425BA




Part #	Tube O.D. x	Α	В	Approx.	List Price
	Male NPTF			Wt. Lbs.	
	(1&2)x3				
38-278	3/8" x 1/4"	0.78	0.91	0.18	12.72
38-279	3/8" x 3/8"	0.85	0.92	0.24	10.58
38-280	1/2" x 3/8"	0.91	0.98	0.36	12.02
38-281	1/2" x 1/2"	1.03	1.18	0.42	33.80
38-282	5/8" x 1/2"	1.09	1.24	0.52	23.59

272AB 1372

1380

45° MALE ELBOW



SAE# 120302BA

Part #	Tube O.D. x	Α	В	Approx.	List Price
	Male NPTF			Wt. Lbs.	
38-287	1/4" x 1/8"	0.49	0.63	0.08	6.68
38-288	1/4" x 1/4"	0.60	0.85	0.10	11.42
38-290	3/8" x 1/4"	0.72	0.86	0.18	7.45
38-291	3/8" x 3/8"	0.75	0.94	0.20	12.57
38-292	3/8" x 1/2"	0.78	1.16	0.22	13.13
38-293*	1/2" x 3/8"	0.82	0.94	0.18	12.05
38-294	1/2" x 1/2"	0.87	1.16	0.24	14.61

* Forged

WORMS

A minister decided that a visual demonstration would add emphasis to his Sunday sermon. Four worms were placed into four separate jars. The first worm was put into a container of alcohol. The second worm was put into a container of cigarette smoke. The third worm was put into a container of chocolate syrup. The fourth worm was put into a container of good clean soil. At the conclusion of the sermon, the Minister reported the following results: The first worm in alcohol - Dead. The second worm in cigarette smoke - Dead. Third worm in chocolate syrup - Dead. Fourth worm in good clean soil - Alive. So the Minister asked the congregation - What can you learn from this demonstration?

A little old woman in the back quickly raised her hand and said, "As long as you drink, smoke and eat chocolate, you won't have worms!"

