

# Charts

## Conversion Chart

INCHES		
FRACTIONS	DECIMALS	MM
—	.0004	.0100
—	.0040	.1000
—	.0100	.2500
1/64	.0156	.3970
—	.0197	.5000
—	.0295	.7500
1/32	.0313	.7940
—	.0394	1.0000
3/64	.0469	1.1910
—	.0590	1.5000
1/16	.0620	1.5880
5/64	.0781	1.9840
—	.0787	2.0000
3/32	.0940	2.3810
—	.0984	2.5000
7/64	.1090	2.7780
—	.1181	3.0000
1/8	.1250	3.1750
—	.1378	3.5000
9/64	.1410	3.5720
5/32	.1560	3.9690
—	.1575	4.0000
11/64	.1720	4.3660
—	.1770	4.5000
3/16	.1875	4.7630
—	.1969	5.0000
13/64	.2030	5.1590
—	.2165	5.5000
7/32	.2190	5.5560
15/64	.2340	5.9530
—	.2362	6.0000
1/4	.2500	6.3500
—	.2559	6.5000
17/64	.2656	6.7470
—	.2756	7.0000
9/32	.2810	7.1440
—	.2953	7.5000
19/64	.2970	7.5410
5/16	.3120	7.9380
—	.3150	8.0000
21/64	.3280	8.3340
—	.3350	8.5000
11/32	.3440	8.7310
—	.3543	9.0000
23/64	.3590	9.1280
—	.3740	9.5000
3/8	.3750	9.5250
25/64	.3910	9.9220

INCHES		
FRACTIONS	DECIMALS	MM
—	.3937	10.0000
13/32	.4060	10.3190
—	.4130	10.5000
27/64	.4220	10.7160
—	.4331	11.0000
7/16	.4380	11.1130
29/64	.4530	11.5090
15/32	.4690	11.9060
—	.4724	12.0000
31/64	.4840	12.3030
—	.4920	12.5000
1/2	.5000	12.7000
—	.5118	13.0000
33/64	.5156	13.0970
17/32	.5310	13.4940
35/64	.5470	13.8910
—	.5512	14.0000
9/16	.5630	14.2880
—	.5710	14.5000
37/64	.5790	14.6840
—	.5906	15.0000
19/32	.5940	15.0810
39/64	.6090	15.4780
5/8	.6250	15.8750
—	.6299	16.0000
41/64	.6406	16.2720
—	.6496	16.5000
21/32	.6560	16.6690
—	.6693	17.0000
43/64	.6720	17.0660
11/16	.6875	17.4630
45/64	.7030	17.8590
—	.7087	18.0000
23/32	.7190	18.2560
—	.7283	18.5000
47/64	.7340	18.6530
—	.7480	19.0000
3/4	.7500	19.0500
49/64	.7656	19.4470
25/32	.7810	19.8440
—	.7874	20.0000
51/64	.7970	20.2410
13/16	.8125	20.6380
—	.8268	21.0000
53/64	.8280	21.0340
27/32	.8440	21.4310
55/64	.8590	21.8280
—	.8662	22.0000

INCHES		
FRACTIONS	DECIMALS	MM
7/8	.8750	22.2250
57/64	.8906	22.6220
—	.9055	23.0000
29/32	.9062	23.0190
59/64	.9220	23.4160
15/16	.9375	23.8130
—	.9449	24.0000
61/64	.9530	24.2090
31/32	.9690	24.6060
—	.9843	25.0000
63/64	.9844	25.0030
1	1.0000	25.4000
—	1.0236	26.0000
1-1/32	1.0312	26.1940
1-1/16	1.0620	26.9880
—	1.0630	27.0000
1-3/32	1.0940	27.7810
—	1.1024	28.0000
1-1/8	1.1250	28.5750
—	1.1417	29.0000
1-5/32	1.1560	29.3690
—	1.1811	30.0000
1-3/16	1.1875	31.1630
1-7/32	1.2190	30.9560
—	1.2205	31.0000
1-1/4	1.2500	31.7500
—	1.2598	32.0000
1-9/32	1.2810	32.5440
—	1.2992	33.0000
1-5/16	1.3120	33.3380
—	1.3386	34.0000
1-11/32	1.3440	34.1310
1-3/8	1.3750	34.9250
—	1.3779	35.0000
1-13/32	1.4060	35.7190
—	1.4173	36.0000
1-7/16	1.4380	36.5130
—	1.4567	37.0000
1-15/32	1.4690	37.3060
—	1.4961	38.0000
1-1/2	1.5000	38.1000
1-17/32	1.5310	38.8940
—	1.5354	39.0000
1-9/16	1.5620	39.6880
—	1.5748	40.0000
1-19/32	1.5940	40.4810
—	1.6142	41.0000
1-5/8	1.6250	41.2750

INCHES		
FRACTIONS	DECIMALS	MM
—	1.6535	42.0000
1-31/32	1.6562	42.0690
1-11/16	1.6875	42.8630
—	1.6929	43.0000
1-23/32	1.7190	43.6560
—	1.7323	44.0000
1-3/4	1.7500	44.4500
—	1.7717	45.0000
1-25/32	1.7810	45.2440
—	1.8110	46.0000
1-13/16	1.8125	46.0380
1-27/32	1.8440	46.8310
—	1.8504	47.0000
1-7/8	1.8750	47.6250
—	1.8898	48.0000
1-29/32	1.9062	48.4190
—	1.9291	49.0000
1-15/16	1.9375	49.2130
—	1.9685	50.0000
1-31/32	1.9690	50.0060
2	2.0000	50.8000
—	2.0079	51.0000
2-1/32	2.0313	51.5940
—	2.0472	52.0000
2-1/16	2.0620	52.3880
—	2.0866	53.0000
2-3/32	2.0940	53.1810
2-1/8	2.1250	53.9750
—	2.1260	54.0000
2-5/32	2.1560	54.7690
—	2.1650	55.0000
2-3/16	2.1875	55.5630
—	2.2047	56.0000
2-7/32	2.2190	56.3560
—	2.2440	57.0000
2-1/4	2.2500	57.1500
2-9/32	2.2810	57.9440
—	2.2835	58.0000
2-5/16	2.3120	58.7380
—	2.3228	59.0000
2-11/32	2.3440	59.5310
—	2.3622	60.0000
2-3/8	2.3750	60.3250
—	2.4016	61.0000