

# Charts

## Conversion Chart

INCHES			INCHES			INCHES			INCHES		
FRACTIONS	DECIMALS	MM	FRACTIONS	DECIMALS	MM	FRACTIONS	DECIMALS	MM	FRACTIONS	DECIMALS	MM
2-13/32	2.4060	61.1190	3-1/4	3.2500	82.5500	4-1/4	4.2500	107.9500	1/4	.2500	6.3500
2-7/16	2.4380	61.9130	—	3.2677	83.0000	4-5/16	4.3120	109.5380	—	.2559	6.5000
—	2.4409	62.0000	3-9/32	3.2810	83.3440	—	4.3307	110.0000	17/64	.2656	6.7470
2-15/32	2.4690	62.7060	—	3.3071	84.0000	4-3/8	4.3750	111.1250	—	.2756	7.0000
—	2.4803	63.0000	3-5/16	3.3120	84.1377	4-7/16	4.4380	112.7130	9/32	.2810	7.1440
2-1/2	2.5000	63.5000	3-11/32	3.3440	84.9314	4-1/2	4.5000	114.3000	—	.2953	7.5000
—	2.5197	64.0000	—	3.3464	85.0000	—	4.5275	115.0000	19/64	.2970	7.5410
2-17/32	2.5310	64.2940	3-3/8	3.3750	85.7250	4-9/16	4.5620	115.8880	5/16	.3120	7.9380
—	2.5590	65.0000	—	3.3858	86.0000	4-5/8	4.6250	117.4750	—	.3150	8.0000
2-9/16	2.5620	65.0880	3-13/32	3.4060	86.5190	4-11/16	4.6875	119.0630	21/64	.3280	8.3340
2-19/32	2.5940	65.8810	—	3.4252	87.0000	—	4.7244	120.0000	—	.3350	8.5000
—	2.5984	66.0000	3-7/16	3.4380	87.3130	4-3/4	4.7500	120.6500	11/32	.3440	8.7310
2-5/8	2.6250	66.6750	—	3.4646	88.0000	4-13/16	4.8125	122.2380	—	.3543	9.0000
—	2.6380	67.0000	3-15/32	3.4690	88.1060	4-7/8	4.8750	123.8250	23/64	.3590	9.1280
2-21/32	2.6560	67.4690	3-1/2	3.5000	88.9000	—	4.9212	125.0000	—	.3740	9.5000
—	2.6772	68.0000	—	3.5039	89.0000	4-15/16	4.9375	125.4130	3/8	.3750	9.5250
2-11/16	2.6875	68.2630	3-17/32	3.5310	89.6940	5	5.0000	127.0000	25/64	.3910	9.9220
—	2.7165	69.0000	—	3.5433	90.0000	—	.0004	.0100	—	.3937	10.0000
2-23/32	2.7190	69.0560	3-9/16	3.5620	90.4877	—	.0100	.2500	13/32	.4060	10.3190
2-3/4	2.7500	69.8500	—	3.5827	91.0000	1/64	.0156	.3970	—	.4130	10.5000
—	2.7559	70.0000	3-19/32	3.5940	91.2810	—	.0197	.5000	27/64	.4220	10.7160
2-25/32	2.7810	70.6439	—	3.6220	92.0000	—	.0295	.7500	—	.4331	11.0000
—	2.7953	71.0000	3-5/8	3.6250	92.0750	—	.0040	.1000	7/16	.4380	11.1130
2-13/16	2.8125	71.4376	3-21/32	3.6560	92.8960	1/32	.0313	.7940	29/64	.4530	11.5090
—	2.8346	72.0000	—	3.6614	93.0000	—	.0394	1.0000	15/32	.4690	11.9060
2-27/32	2.8440	72.2314	3-11/16	3.6875	93.6630	3/64	.0469	1.1910	—	.4724	12.0000
—	2.8740	73.0000	—	3.7008	94.0000	—	.0590	1.5000	31/64	.4840	12.3030
2-7/8	2.8750	73.0250	3-23/32	3.7190	94.4560	1/16	.0620	1.5880	—	.4920	12.5000
2-29/32	2.9062	73.8190	—	3.7401	95.0000	5/64	.0781	1.9840	1/2	.5000	12.7000
—	2.9134	74.0000	3-3/4	3.7500	92.2500	—	.0787	2.0000	—	.5118	13.0000
2-15/16	2.9375	74.6130	—	3.7795	96.0000	3/32	.0940	2.3810	33/64	.5156	13.0970
—	2.9527	75.0000	3-25/32	3.7810	96.0440	—	.0984	2.5000	17/32	.5310	13.4940
2-31/32	2.9690	75.4060	3-13/16	3.8125	96.8380	7.64	.1090	2.7780	35/64	.5470	13.8910
—	2.9921	76.0000	—	3.8189	97.0000	—	.1181	3.0000	—	.5512	14.0000
3	3.0000	76.2000	3-26/32	3.8440	97.6310	1/8	.1250	3.1750	9/16	.5630	14.2880
3-1/32	3.0312	76.9940	—	3.8583	98.0000	—	.1378	3.5000	—	.5710	14.5000
—	3.0315	77.0000	3-7/8	3.8750	98.4250	9/64	.1410	3.5720	37/64	.5790	14.6840
3-1/16	3.0620	77.7880	—	3.8976	99.0000	5/32	.1560	3.9690	—	.5906	15.0000
—	3.0709	78.0000	3-29/32	3.9062	99.2190	—	.1575	4.0000	19/32	.5940	15.0810
3-3/32	3.0940	78.5810	—	3.9370	100.0000	11/64	.1720	4.3660	39/64	.6090	15.4780
—	3.1102	79.0000	3-15/16	3.9375	100.0130	—	.1770	4.5000	5/8	.6250	15.8750
3-1/8	3.1250	79.3750	3-31/32	3.9690	100.8060	3/16	.1875	4.7630	—	.6299	16.0000
—	3.1496	80.0000	—	3.9764	101.0000	—	.1969	5.0000	41/64	.6406	16.2720
3-5/32	3.1560	80.1690	4	4.0000	101.6000	13/64	.2030	5.1590	—	.6496	16.5000
3/16	3.1875	80.9630	4-1/16	4.0620	103.1880	—	.2165	5.5000	21/32	.6560	16.6690
—	3.1890	81.0000	4-1/8	4.1250	104.7750	7/32	.2190	5.5560	—	—	—
3-7/32	3.2190	81.7560	—	4.1338	105.0000	15/64	.2340	5.9530	—	—	—
—	3.2283	82.0000	4-3/16	4.1875	106.3630	—	.2362	6.0000	—	—	—