

















 <p><b>30° Flare</b></p>	<p><b>F3T4</b> BSPT / 30° Flare</p>  <p>15</p>	<p><b>PNMT4</b> Plug</p>  <p>15</p>	<p><b>FNMT4</b> Cap</p>  <p>15</p>	<p><b>V3T4</b> BSPT / 30° Flare</p>  <p>15</p>	<p><b>C3T4</b> BSPT / 30° Flare</p>  <p>15</p>
 <p><b>60° Cone</b></p>	<p><b>F3P4</b> BSPT / 60° Cone</p>  <p>15</p>	<p><b>HP4</b> Union</p>  <p>16</p>	<p><b>G3P4</b> BSPT / 60° Cone</p>  <p>16</p>	<p><b>PNMP4</b> Plug</p>  <p>16</p>	<p><b>F63P4</b> 60° Swivel / BSPT</p>  <p>16</p>
<p><b>G63P4</b> 60° Swivel / BSPT</p>  <p>16</p>	<p><b>HP46</b> Union Swivel</p>  <p>16</p>	<p><b>FNMP4</b> Cap</p>  <p>17</p>	<p><b>C3P4</b> BSPT / 60° Cone</p>  <p>17</p>	<p><b>V3P4</b> BSPT / 60° Cone</p>  <p>17</p>	
 <p><b>B2351 Port</b></p>	<p><b>P47OMN</b> Hex Head Plug</p>  <p>17</p>				

**O-Rings and Seals** (Shown in Section O)

 <p><b>JIS O-Rings and Seals</b></p>	<p><b>JIS B2351 O-Ring</b></p>  <p>O6</p>
---	--

Dimensions and pressures for reference only, subject to change.