




















<p>60° Cone BSP Adapters</p>	<p>Straights</p>	<p>HMK4 Union</p>  <p>J6</p>	<p>WMK4WL4NM Bulkhead Union</p>  <p>J6</p>	<p>F6MK4 60° Swivel / 60° Cone</p>  <p>J6</p>	<p>H6MK4 Swivel Union</p>  <p>J6</p>
<p>FMK4 NPTF / 60° Cone</p>  <p>J7</p>	<p>F3MK4 BSPT / 60° Cone</p>  <p>J7</p>	<p>G4MK4 BSPP / 60° Cone</p>  <p>J7</p>	<p>Elbows</p>	<p>EMK4 Union Elbow</p>  <p>J8</p>	<p>C6MK4 60° Swivel / 60° Cone</p>  <p>J8</p>
<p>E6MK4 Swivel Union</p>  <p>J8</p>	<p>Tees</p>	<p>JMK4 Union Tee</p>  <p>J9</p>	<p>S6MK4 60° Swivel Branch Tee</p>  <p>J9</p>	<p>R6MK4 60° Swivel Run Tee</p>  <p>J9</p>	<p>J6MK4 Swivel Union Tee</p>  <p>J9</p>
<p>Plug Caps</p>	<p>PNMK4 Hex Head Plug</p>  <p>J7</p>	<p>FNMK4 Cap</p>  <p>J8</p>			

Conversion Adapters (Shown in Section L)

<p>K4 BSP Conversion Adapters</p>	<p>XHMK46 37° Flare / BSPP Swivel</p>  <p>L5</p>	<p>XEMK46 37° Flare / BSPP Swivel</p>  <p>L5</p>
--	--	--

O-Rings and Seals (Shown in Section O)

<p>K4 BSP O-Rings and Seals</p>	<p>D9DT BSPP Bonded Seal</p>  <p>O6</p>
--	---

Dimensions and pressures for reference only, subject to change.