

A Dixon Quick Coupling representative is ready to assist you at

| Competitor's Part Number | Dixon Quick Coupling Number | Competitor Name | Page No | Competitor's Part Number | Dixon Quick Coupling Number | Competitor Name | Page No |
|--------------------------|-----------------------------|-----------------|---------|--------------------------|-----------------------------|-----------------|---------|
| F. IR34V NPT | 6AGF6-PV | Stucchi | 65 | FBM-24 | 12WDP-B | PCI | 82 |
| F. IR38 NPT | 3AGF3 | Stucchi | 65 | FC3 | 4FF3 | Hofmann | 19 |
| F. IR38V NPT | 3AGF3-PV | Stucchi | 65 | FC3-Q | 4DF3-B | Hofmann | 19 |
| F. IRB 18 NPT | 1HF1 | Stucchi | 56 | FC4 | 4FF4 | Hofmann | 19 |
| F. IRB100 NPT | 8HF8 | Stucchi | 56 | FC4-Q | 4DF4-B | Hofmann | 19 |
| F. IRB100 NPT | H8F8 | Stucchi | 57 | FC5 | 4FF6 | Hofmann | 19 |
| F. IRB12 NPT | 4HF4 | Stucchi | 56 | FC5-Q | 4DF6-B | Hofmann | 19 |
| F. IRB14 NPT | 2HF2 | Stucchi | 56 | FD40-1000-04-04 | 2DF2-B | Aeroquip | 19 |
| F. IRB34 NPT | 6HF6 | Stucchi | 56 | FD40-1000-04-06 | 3DF2-B | Aeroquip | 19 |
| F. IRB38 NPT | 3HF3 | Stucchi | 56 | FD40-1000-06-04 | 2DF3-B | Aeroquip | 19 |
| F. IRBOV100 NPT | 8HF8-B | Stucchi | 56 | FD40-1000-06-06 | 3DF3-B | Aeroquip | 19 |
| F. IRBOV12 NPT | 4HF4-B | Stucchi | 56 | FD40-1000-08-06 | 3DF4-B | Aeroquip | 19 |
| F. IRBOV14 NPT | 2HF2-B | Stucchi | 56 | FD40-1000-08-08 | 4DF4-B | Aeroquip | 19 |
| F. IRBOV18 NPT | 1HF1-B | Stucchi | 56 | FD40-1001-04-04 | 2DM2-B | Aeroquip | 20 |
| F. IRBOV34 NPT | 6HF6-B | Stucchi | 56 | FD40-1001-04-06 | 3DM2-B | Aeroquip | 20 |
| F. IRBOV38 NPT | 3HF3-B | Stucchi | 56 | FD40-1001-06-04 | 2DM3-B | Aeroquip | 20 |
| F. IRBX100 NPT | 8HF8-SS | Stucchi | 56 | FD40-1001-06-06 | 3DM3-B | Aeroquip | 20 |
| F. IRBX12 NPT | 4HF4-SS | Stucchi | 56 | FD40-1001-08-06 | 3DM4-B | Aeroquip | 20 |
| F. IRBX14 NPT | 2HF2-SS | Stucchi | 56 | FD40-1001-08-08 | 4DM4-B | Aeroquip | 20 |
| F. IRBX34 NPT | 6HF6-SS | Stucchi | 56 | FD40-1013-02-04 | D2F1 | Aeroquip | 19 |
| F. IRBX34 NPT | H6F6-SS | Stucchi | 57 | FD40-1013-04-04 | D2F2 | Aeroquip | 19 |
| F. IRBX38 NPT | 3HF3-SS | Stucchi | 56 | FD40-1013-06-04 | D2F3 | Aeroquip | 19 |
| F. IRS12VA NPT | 4AGF4-PS | Stucchi | 65 | FD40-1013-06-06 | D3F3 | Aeroquip | 19 |
| F. IVHP 3/8 NPT | 3TF3 | Stucchi | 88 | FD40-1013-08-06 | D3F4 | Aeroquip | 19 |
| F. VEP13 1/2 NPT | 4VEPF4 | Stucchi | 84 | FD40-1013-08-08 | D4F4 | Aeroquip | 19 |
| F. VEP13 3/4 SAE | 4VEPOF6 | Stucchi | 84 | FD40-1014-02-04 | D2M1 | Aeroquip | 20 |
| F. VEP15 3/4 NPT | 6VEPF6 | Stucchi | 84 | FD40-1014-04-04 | D2M2 | Aeroquip | 20 |
| F. VEP15 3/4 SAE | 6VEPOF6 | Stucchi | 84 | FD40-1014-04-06 | D3M2 | Aeroquip | 20 |
| F. VEP17 1" NPT | 8VEPF8 | Stucchi | 84 | FD40-1014-06-04 | D2M3 | Aeroquip | 20 |
| F. VEP17 1" SAE | 8VEPOF8 | Stucchi | 84 | FD40-1014-06-06 | D3M3 | Aeroquip | 20 |
| F. VEP21 114 NPT | 10VEPF10 | Stucchi | 84 | FD40-1014-06-08 | D4M3 | Aeroquip | 20 |
| F. VEP30 112 NPT | 12VEPF12 | Stucchi | 84 | FD40-1014-08-06 | D3M4 | Aeroquip | 20 |
| F. W10F10-B | 10WF10-B | Stucchi | 83 | FD40-1014-08-08 | D4M4 | Aeroquip | 20 |
| F. W12F12-B | 12WF12-B | Stucchi | 83 | FD40-1016-04-04 | D2B2 | Aeroquip | 21 |
| F. W6F6-B | 6WF6-B | Stucchi | 83 | FD40-1019-04-04 | D2S2 | Aeroquip | 21 |
| F. W8F8-B | 8WF8-B | Stucchi | 83 | FD40-1019-06-06 | D3S3 | Aeroquip | 21 |
| FA1 | 2FF1-B | Hofmann | 19 | FD40-1019-08-08 | D4S4 | Aeroquip | 21 |
| FA2 | 2FF2-B | Hofmann | 19 | FD41-1000-04-04 | 2MF2-PL | Aeroquip | 26 |
| FA3 | 2FF3-B | Hofmann | 19 | FD41-1000-06-04 | 3MF3-PL | Aeroquip | 26 |
| FA3-Q | 2DF3-B | Hofmann | 19 | FD41-1014-04-04 | M2M2 | Aeroquip | 27 |
| FB-08-F | 6WF4-B | PCI | 83 | FD42-1011-02-04 | 2FM1-B | Aeroquip | 20 |
| FB-08-F-H | 6WF4-B-HN | PCI | 83 | FD43-1001-02-04 | 2FF1-B | Aeroquip | 19 |
| FB-08-M | W6F4-B | PCI | 83 | FD43-1001-04-04 | 2FF2-B | Aeroquip | 19 |
| FB12 | P4F6-B | National | 40 | FD43-1001-04-06 | 3FF2 | Aeroquip | 19 |
| FB-12-F | 6WF6-B | PCI | 83 | FD43-1001-06-04 | 2FF3-B | Aeroquip | 19 |
| FB-12-F-H | 6WF6-B-HN | PCI | 83 | FD43-1001-06-06 | 3FF3 | Aeroquip | 19 |
| FB-12-M | W6F6-B | PCI | 83 | FD43-1001-08-06 | 3FF4 | Aeroquip | 19 |
| FB-16/1-NPT-F | 8WF8-B | Faster | 83 | FD43-1001-08-08 | 4FF4 | Aeroquip | 19 |
| FB-16/1-NPT-M | W8F8-B | Faster | 83 | FD43-1011-04-04 | 2FM2-B | Aeroquip | 20 |
| FB-16-F | 8WF8-B | PCI | 83 | FD43-1011-06-04 | 2FM3-B | Aeroquip | 20 |
| FB-16-F-H | 8WF8-B-HN | PCI | 83 | FD43-1011-06-06 | 3FM3 | Aeroquip | 20 |
| FB-16-M | W8F8-B | PCI | 83 | FD43-1011-08-06 | 3FM4 | Aeroquip | 20 |
| FB2 | 3FF2 | Hofmann | 19 | FD43-1011-08-08 | 4FM4 | Aeroquip | 20 |
| FB-20/114-NPT-F | 10WF10-B | Faster | 83 | FD43-1031-04-04 | 2FB2-B | Aeroquip | 21 |
| FB-20/114-NPT-M | W10F10-B | Faster | 83 | FD43-1031-06-04 | 2FB3-B | Aeroquip | 21 |
| FB-20-F | 10WF10-B | PCI | 83 | FD45-1002-02-02 | H1F1 | Aeroquip | 57 |
| FB-20-F-H | 10WF10-B-HN | PCI | 83 | FD45-1002-04-04 | H2F2 | Aeroquip | 57 |
| FB-20-M | W10F10-B | PCI | 83 | FD45-1002-06-06 | H3F3 | Aeroquip | 57 |
| FB-24-F | 12WF12-B | PCI | 83 | FD45-1002-08-10 | H4F4 | Aeroquip | 57 |
| FB-24-F-H | 12WF12-B-HN | PCI | 83 | FD45-1002-12-12 | H6F6 | Aeroquip | 57 |
| FB-24-M | W12F12-B | PCI | 83 | FD45-1002-16-16 | H8F8 | Aeroquip | 57 |
| FB3 | 3FF3 | Hofmann | 19 | FD45-1003-02-02 | 1HF1 | Aeroquip | 56 |
| FB4 | 3FF4 | Hofmann | 19 | FD45-1003-04-04 | 2HF2 | Aeroquip | 56 |
| FB8 | P4F4-B | National | 40 | FD45-1003-06-06 | 3HF3 | Aeroquip | 56 |
| FBF-12 | W6DC-B | PCI | 82 | FD45-1003-08-10 | 4HF4 | Aeroquip | 56 |
| FBF-16 | W8DC-B | PCI | 82 | FD45-1003-12-12 | 6HF6 | Aeroquip | 56 |
| FBF-20 | W10DC-B | PCI | 82 | FD45-1003-16-16 | 8HF8 | Aeroquip | 56 |
| FBF-24 | W12DC-B | PCI | 82 | FD45-1004-12-12 | H6F6-S | Aeroquip | 57 |
| FBM-12 | 6WDP-B | PCI | 82 | FD45-1040-02 | H1DC | Aeroquip | 55 |
| FBM-16 | 8WDP-B | PCI | 82 | FD45-1040-04 | H2DC | Aeroquip | 55 |
| FBM-20 | 10WDP-B | PCI | 82 | FD45-1040-06 | H3DC | Aeroquip | 55 |

Interchange